

Digital pressure switch
for energy-saving control ejector



(Supply valve N.C. and N.O. specifications)

Before Use

Thank you for purchasing the SMC ZL Series with Digital Pressure Switch. Please read the operation manual carefully before operating the product and make sure you understand its capabilities and limitations. Please keep the operation manual handy for future reference.

To obtain the operation manual about this product, please refer to the SMC website (URL <http://www.smeworld.com>) or contact SMC directly.

Safety Instructions

These safety instructions are intended to prevent hazardous situations and/or equipment damage.

These instructions indicate the level of potential hazard with the labels of "Caution", "Warning" or "Danger". They are all important notes for safety and must be followed in addition to International standards (ISO/IEC) and other safety regulations.

To obtain operating the ejector which is mounted on this product, please refer to "Handling Precautions for SMC Products" for vacuum equipment on our general product catalogue or precaution for each product.

Caution: Operator error could result in injury or equipment damage.

Warning: Operator error could result in serious injury or loss of life.

Danger: In extreme conditions, there is a possibility of serious injury or loss of life.

Operator

This operation manual is intended for those who have knowledge of machinery using pneumatic equipment, and have sufficient knowledge of assembly, operation and maintenance of such equipment. Only those persons are allowed to perform assembly, operation and maintenance.

Read and understand this operation manual carefully before assembling, operating or providing maintenance to the product.

Safety Instructions

Warning

Do not disassemble, modify (including changing the printed circuit board) or repair. An injury or failure can result.

Do not use the product except for energy-saving control ejector. Fire, malfunction, or damage to the product or the system can result.

Do not operate the product outside of the specifications. Do not use for flammable or harmful fluids. Fire, malfunction, or damage to the product can result. Verify the specifications before use.

Do not operate in an atmosphere containing flammable or explosive gases. Fire or an explosion can result. This product is not designed to be explosion proof.

Do not use the product in a place where static electricity is a problem. Otherwise it can cause failure or malfunction of the system.

If using the product in an interlocking circuit:
Provide a double interlocking system, for example a mechanical system
Check the product regularly for proper operation
Otherwise malfunction can result, causing an accident.

The following instructions must be followed during maintenance:
Turn off the power supply
Stop the air supply, exhaust the residual pressure and verify that the air is released before performing maintenance.
Otherwise an injury can result.

Verify the system sufficiently before judging the applicability when a permeable workpiece is to be sucked. Rapid decrease in vacuum pressure during suction of the workpiece may cause the ejector to fail to restart in time, causing injury or damage to the system because of the suction failure.


Caution

Do not touch the terminals and connectors while the power is on. Otherwise electric shock, malfunction or damage to the product can result.

Perform sufficient trial run. Otherwise, injury or damage to the system can result due to suction failure depending on the conditions of the suction of the workpiece or the pressure switch settings. Perform sufficient verification before using this product.

After maintenance is complete, perform appropriate functional inspections and leak tests. Stop operation if the equipment does not function properly or there is a leakage of fluid. When leakage occurs from parts other than the piping, the product might be faulty. Disconnect the power supply and stop the fluid supply. Do not apply fluid under leaking conditions. Safety cannot be assured in the case of unexpected malfunction.

Names and Functions of Product



Output (OUT1) display (Green): LED is ON when the switch output (OUT1) is turned ON.

Output (OUT2) display (Red): LED is ON when the supply pilot valve is ON.

LED display: Displays the current status of pressure, setting mode and error code.

button (UP): Selects the mode or increases the ON/OFF set value.

Press this button to change to the peak display mode.

button (DOWN): Selects the mode or decreases the ON/OFF set value.

Press this button to change to the bottom display mode.

button (SET): Press this button to change to either mode and to set a value.

Product specification identification symbol : ① ② ③

① Supply valve specification :

R(Supply valve (N.C.)), Q(Supply valve (N.O.))

② Output specification :


A(NPN open collector 2 outputs), B(PNP open collector 2 outputs)

③ Unit specification :

Nil(With unit switching function), M(SI unit only), P(With unit switching function (Initial value psi))


Internal circuit and wiring example

- NPN output type
NPN open collector 2 outputs(OUT1:General purpose,OUT2:Valve control),
Max. applied voltage 26.4 VDC, Max. load current 80 mA, Residual voltage 2 V or less



PNP output type

- PNP output type
PNP open collector 2 outputs(OUT1:General purpose,OUT2:Valve control),
Max. load current 80 mA, Residual voltage 2 V or less



Easy setting (Supply valve (N.O.))

See below for the energy saving control operation and the set values which are preset to the switch.

If the operation shown below does not cause any problems, keep these setting.

Operation of OUT1

When the pressure exceeds the set value (P_{-1}), the pressure switch turns ON. When the pressure decreases below the set value (P_{-1}) by the hysteresis value (H_{-1}), the switch turns OFF.

The default settings are P_{-1} : -70.0 kPa and H_{-1} : 10.0 kPa.

When a power outage occurs or the power supply is turned OFF, OUT1 turns OFF. When the power is restored, an output is made about one second later in accordance with the setting.

Operation of OUT2

When the adsorption directive signal is OFF, the supply valve (OUT2) is open, generates vacuum, and starts adsorption.

When the vacuum pressure reaches the set value (P_{-1}), the supply pilot valve is close.

After the supply pilot valve is closed, the vacuum pressure will decrease, when the vacuum pressure drops below (P_{-1}) by the amount set in (H_{-2}) the supply pilot valve will open again and increase vacuum pressure.

After that, supply pilot valve will open and close repeatability.

Default setting is H_{-2} : 5.0 kPa.

When the vacuum generation is stopped, the adsorption directive signal is turned ON.

When a power outage occurs or the power supply is turned OFF, the supply valve (OUT2) is open and generates vacuum (when air is supplied).

Adsorption directive signal (FUNC)
ON OFF

Pilot valve for air supply (Energy saving automatic control: OUT2)
OPEN CLOSE

Switch output (OUT1)
ON OFF

Atmospheric pressure

Vacuum port(V) pressure

High vacuum

*: When turning off the supply pilot valve with a vacuum pressure which is higher than the set value (P_{-1}), and other setting methods, refer to the operation manual which can be obtained from the SMC website (URL <http://www.smeworld.com>).

How to change the set value

[Normal output (OUT1)]

(1) Press the button once in measurement mode.



(2) "P_{-1}" and the set value are displayed alternately.

Display in turn

Normal output



(3) Press the button or button to change the set value.

The button is to increase vacuum pressure and the button is for decrease.

• Press the button once to increase the value by one digit, press and hold to continuously increase.



• Press the button once to decrease the value by one digit, press and hold to continuously decrease.



(4) Press the button to complete the setting of "P_{-1} ". The display shows [H_{-1}] and the set value alternately. The button is to increase and the button is to decrease the set value.



(5) Press the button to complete the setting of "H_{-2} ". The display shows [H_{-2}] and the set value alternately. The button is to increase and the button is to decrease the set value.



(6) Press the button to complete the setting.

When the reversed output is changed, the following parameters are displayed, and each set value can be changed, using the method shown above.

[Reversed output (OUT1)]

Measurement mode → → → → → Complete

Installation

Wiring

Connection

- Connections should only be made with the power supply turned off.
- Use a separate routes for the Pressure switch wiring and any power or high voltage wiring. Otherwise, malfunction may result due to noise.


Ensure that the FG terminal is connected to ground when using a commercially available switch-mode power supply. When a switch-mode power supply is connected to the product, switching noise will be superimposed and the product specification can no longer be met.

This can be prevented by inserting a noise filter, such as a line noise filter and ferrite core, between the switch-mode power supply and the product, or by using a series power supply instead of a switch-mode power supply.

Connector

Connecting/Disconnecting

- When mounting the connector, insert it straight into the socket, holding the lever and connector body, and fit the hook of the lever into the groove in the housing to lock.
- When removing the connector, press down the lever to release the hook from the groove and pull the connector straight out.



• Pin No. of the Connector (Power supply and output cable for the digital pressure switch and pilot valve)

Easy setting (Supply valve (N.C.))

See below for the energy saving control operation and the set values which are preset to the switch.

If the operation shown below does not cause any problems, keep these setting.

Operation of OUT1

When the pressure exceeds the set value (P_{-1}), the pressure switch turns ON.

When the pressure decreases below the set value (P_{-1}) by the hysteresis value (H_{-1}), the switch turns OFF.

The default settings are P_{-1} : -70.0 kPa and H_{-1} : 10.0 kPa.

Operation of OUT2

When the adsorption directive signal is ON, the supply valve (OUT2) is open, generates vacuum, and starts adsorption.

When the vacuum pressure reaches the set value (P_{-1}), the supply pilot valve is close.

After the supply pilot valve is closed, the vacuum pressure will decrease, when the vacuum pressure drops below (P_{-1}) by the amount set in (H_{-2}) the supply pilot valve will open again and increase vacuum pressure.

After that, supply pilot valve will open and close repeatability.

Default setting is H_{-2} : 5.0 kPa.

Adsorption directive signal ON (FUNC)
ON OFF

Pilot valve for air supply (Energy saving automatic control: OUT2)
OPEN CLOSE

Switch output (OUT1)
ON OFF

Atmospheric pressure

Vacuum port (V) pressure


High vacuum

*: When turning off the supply pilot valve with a vacuum pressure which is higher than the set value (P_{-1}), and other setting methods, refer to the operation manual which can be obtained from the SMC website (URL <http://www.smeworld.com>).

Function Setting



Measurement mode

The measurement mode is the condition where the pressure is detected and indicated, and the switch function is operating. This is the basic mode, and other modes should be selected for setting change and other function setting changes.



Function selection mode

In measurement mode, press the **F** button for 2 seconds or longer to display [F 0]. Select to display the function setting to be changed, [F 0]. Press the **F** button for 2 seconds or longer in function selection mode to return to measurement mode.



Other Settings

○Peak/Bottom hold value indication

○Zero clear

○Zero clear of indication

Indication is reset to zero when **④** and **⑤** buttons are pressed simultaneously for 1 second. For the first operation, perform zero clear without pressure supply.

○Key lock

Refer to the operation manual on the SMC website ([URL http://www.smeworld.com](http://www.smeworld.com)) for the settings shown above.

Maintenance

How to reset the product for power cut or forcible de-energizing

The setting of the product will be retained as it was before a power cut or de-energizing.

The output condition is also basically recovered to that before a power cut or de-energizing, but may change depending on the operating environment. Therefore, check the safety of the whole system before operating the product.

If the system is using accurate control, wait until it has warmed up.

(Approximately 10 minutes)

Troubleshooting

■Error indication

This function is to display error location and content when a problem or an error occurs.

Error Name	Error Display	Error Type	Troubleshooting Method
Over current Error	 	The switch output load current is more than 80 mA.	Turn the power off and remove the cause of the over current. Then turn the power on.
Zero-clear Error		During the zero clear operation, pressure above ±3.5%F.S. has been applied. After 1 second, the mode will return to measurement mode. The zero clear range can vary ±1%F.S. with individual product differences.	Perform zero clear operation again after restoring the applied pressure to an atmospheric pressure condition.
Pressurizing Error		Pressure has exceeded the upper limit of the set pressure range.	Reset applied pressure to a level within the set pressure range.
		Pressure has exceeded the lower limit of the set pressure range.	Reset applied pressure to a level within the set pressure range.
System Error	 	Displayed in the case of an internal data error.	Turn the power off and turn it on again. If resetting fails, an investigation by SMC Corporation will be required.

If the error can not be reset after the above measures are taken, then please contact SMC.

Specification

Refer to the operation manual on the SMC website ([URL http://www.smeworld.com](http://www.smeworld.com)).

SMC Corporation

[URL http://www.smeworld.com](http://www.smeworld.com)

Akihabara UDX 15F, 4-14-1, Sotokanda, Chiyoda-ku, Tokyo 101-0021, JAPAN

Phone: +81 3-5207-8249 Fax: +81 3-5298-5362

Note: Specifications are subject to change without prior notice and any obligation on the part of the manufacturer.

© 2022 SMC Corporation All Rights Reserved

ZL3-OM00201E

省エネ機能付真空用圧力スイッチ (供給弁N.C.、N.O.仕様用) ご使用の前に



このたびは SMC 省エネ機能付真空用圧力スイッチ付 ZL シリーズをお買いあげいただきまして、誠にありがとうございます。
この商品を安全に正しくご使用いただくために、お使いになる前に取扱説明書をよくお読みになり、十分に理解してください。お読みになった後も手元においてご使用ください。

本製品の取扱説明書については、当社ホームページ(URL <http://www.smeworld.com>)でご確認いただく、もしくは、お買い上げいただいた販売店にお問合せください。

安全上のご注意

ここに示した注意事項は、製品を安全に正しくお使いいただき、あなたや他の人々への危害や損害を未然に防止するためのものです。
これらの事項は、危害や損害の大きさと切迫の程度を明示するために、「注意」「警告」「危険」の三つに区分されています。いずれも安全に関する重要な内容ですから、国際規格(ISO/IEC)、日本産業規格(JIS)およびその他の安全法規に加えて、必ず守ってください。

本製品を取扱うエジクタの取扱いについては、SMC 総合カタログ記載の真空機器/共通注意事項および製品個別注意事項を参照してください。

△ 注意: 取扱いを誤った時に、人が傷害を負う危険が想定される時、および物的損害のみの発生が想定されるもの。

△ 警告: 取扱いを誤った時に、人が死亡もしくは重傷を負う可能性が想定されるもの。

△ 危険: 切迫した危険の状態で、回避しないと死亡もしくは重傷を負う可能性が想定されるもの。

■ 図記号の説明

図記号	図記号の意味
	禁止(してはいけないこと)を示します。 具体的な禁止内容は、図記号の中や近くに絵や文章で指示します。
	指示する行為の強制(必ずすること)を示します。 具体的な指示内容は、図記号の中や近くに絵や文章で指示します。

■ 取扱い者について

①この取扱説明書は、空気圧機器を使用した機械・装置の組立・操作・保守点検するかたで、これらの機器に対して十分な知識と経験をお持ちのかたを対象にしています。
組立・操作・保守点検の実施は、このかたに限定させていただきます。

②組立・操作・保守点検に当たっては、この本書をよく読んで内容を理解した上で実施してください。

■ 安全上のご注意


△ 警告

	■分解・改造(基板の組み替え含む)・修理は行わないこと けが、故障の恐れがあります。
	■省エネ制御真空エジクタ以外には使用しないこと。 火災・誤動作、圧カスイッチやシステムの破損の恐れがあります。
	■仕様範囲を超えて使用しないこと 引火性もしくは人体に影響のあるガス・流体には使用しないでください。 仕様範囲を超えて使用すると、火災・誤動作・圧カスイッチ破損の原因となります。 仕様を確認の上、ご使用ください。
	■可燃性ガス・爆発性ガスの雰囲気では使用しないこと 火災・爆発の恐れがあります。 この圧カスイッチは、防爆構造ではありません。
	■静電気の帯電が問題になる場所には使用しないこと システム不良や故障の原因になります。
	■インターロック回路に使用する場合は ・別系統による(機械式の保護機能など)多重のインターロックを設けること ・正常に動作していることの点検を実施すること 誤動作による、事故の恐れがあります。
	■保守点検をするときは ・供給電源をオフにすること ・供給しているエアを止めて、配管中の圧縮空気を排気し、大気開放状態を確認してから実施すること けがの恐れがあります。
	■通気性のあるワークを吸着する場合には、システムの十分な検証を行ってから使用の判断をすること ワーク吸着中に急激に真空圧力が低下するとエジェクタ再起動が間に合わない場合があり、吸着不良によるけが、システム破損の恐れがあります。
	■通電中は端子、コネクタに触らないこと 通電中に端子やコネクタに触ると、感電・誤動作・スイッチの破損の恐れがあります。

△ 注意

	■試運転の徹底 ワークの吸着条件と圧カスイッチの設定条件によっては吸着不良によるけが、システムの破損の恐れがあります。 使用前に十分な検証を行ない、使用的の判断をしてください。
	■保守点検完了後に適正な機能検査、漏れ検査を実施すること 正常に機器が動作しない、漏れがあるなどの異常の場合には運転を停止してください。 配管部以外からの漏れが発生した場合、圧カスイッチが破損している場合があります。 電源を切り直し液体の供給を停止してください。 漏れがある状態で絶対に液体を印加しないでください。 意図しない誤操作により、安全が確保できなくなる可能性があります。

製品各部の名称とはたらき



- ① (1) (2) (3) 出力(OUT1)表示(緑)：スイッチ出力 OUT1 が ON 時に点灯します。
- ② (2) 出力(OUT2)表示(赤)：供給用バイロット弁が ON 時に点灯します。
- ③ LED 表示：現在の圧力状態、設定モードの状態、エラーコードを表示します。
- ④ ボタン(UP)：モードの選択および ON/OFF 設定値を増加させます。
- ⑤ ボタン(DOWN)：モードの選択および ON/OFF 設定値を減少させます。
- ⑥ ボタン(SET)：各モードの変更と設定値の確定に使用します。


製品仕様識別記号:

- ① 供給弁仕様: R(供給弁 N.C.)、Q(供給弁 N.O.)
- ② 出力仕様: A(PNP オープンコレクタ 2 出力)、B(PNP オープンコレクタ 2 出力)
- ③ 単位仕様: 無(単位切換機能付)、M(単位固定)、P(単位切換機能付(初期 psi))


●デジタル圧力スイッチとバイロット弁 電源・出力接続ケーブルのコネクタピン番号 (圧カスイッチ用ケーブル Ass'y)

○内部回路と配線例

- ・ NPN 出力タイプ
NPN オープンコレクタ 2 出力 (OUT1: 汎用、OUT2: バルブ制御用)、最大印加電圧 DC26.4 V、最大負荷電流 80 mA、残留電圧 2 V 以下



- ・ PNP 出力タイプ
PNP オープンコレクタ 2 出力 (OUT1: 汎用、OUT2: バルブ制御用)、最大負荷電流 80 mA、残留電圧 2 V 以下



※: 設定値(P_1)よりも高い真空圧で供給用バイロット弁を OFF する場合等、その他の設定方法については、当社ホームページ(URL <http://www.smeworld.com>)より取扱説明書をご確認ください。

簡易設定(供給弁 N.O. 仕様)

スイッチ本体に予め設定されている省エネ制御の動作と設定値は以下の通りです。
以下に示す動作にて支障のない場合は、そのままご使用ください。

OUT1 の動作

圧力が設定値(P_1)を超えるとスイッチが ON します。
圧力が設定値(H_1)から応差(H_1)以上下ると、スイッチが OFF します。
工場出荷時は、P_1: -70.0 kPa H_1: 10.0 kPa に設定されています。

停電および電源 OFF 時は、OUT1 は OFF となります。電源復帰後、約 1 秒後に設定に準じた出力をします。


OUT2 の動作

吸着指令信号が OFF 時に供給弁(OUT2)が開状態となり、真空を発生させ吸着を開始します。
真空度が設定値(P_1)に達すると、供給用バイロット弁を閉状態にします。

その後、真空度が低下する((P_1)から(H_2)下がる)と、再度供給用バイロット弁が開状態となり真空度を保持します。

以降、供給用バイロット弁は開状態、閉状態を繰り返します。
工場出荷時は、H_2: 5.0 kPa に設定されています。

真空発生停止する場合は、吸着指令信号を ON します。
停電および電源 OFF 時は供給弁(OUT2)が開状態となり、真空を発生させます(エアが供給されている場合)。



※: 設定値(P_1)よりも高い真空圧で供給用バイロット弁を OFF する場合等、その他の設定方法については、当社ホームページ(URL <http://www.smeworld.com>)より取扱説明書をご確認ください。

<設定値変更の操作方法>

「OUT1 正転出力時」

① 測定モード時(に)ボタンを 1 回押してください。

注記: 機能の設定の「測定モードとは」を参照。



② [P_1] と設定値が交互に表示されます。

交互に表示
正転出力時 -700

③ ④ または ボタンを押して、設定値を変更してください。
④ ボタンで真空側へ増加、 ボタンで正圧側へ減少ができます。

⑤ ボタンを 1 回押すと数値が増加し、押し続けると連続して増加します。

-700 -699

⑥ ボタンを押すと[H_1]と設定値が交互に表示されます。
④ ボタンで設定値の増加、 ボタンで設定値の減少ができます。

H_1 100


⑤ ボタンを押すと[H_2]と設定値が交互に表示されます。
④ ボタンで設定値の増加、 ボタンで設定値の減少ができます。

配線方法

■配線方法


○接続について

- 接続作業は電源を切断した状態で行ってください。
- 配線は単独の配線経路を使用してください。動力線や高圧線と同一配線経路を使用すると、ノイズによる誤作動の原因となります。
- 市販のスイッチング電源を使用する場合は、かならず FG 端子に接地をしてください。
- 市販のスイッチング電源に接続して使用する場合、スイッチングノイズが重複され、製品仕様を満足できなくなります。その場合は、スイッチング電源との間に、ラインノイズフィルタ、フェライトなどのノイズフィルタを挿入す。



○コネクタの着脱方法

- コネクタを装着する場合、レバー部とコネクタ本体を指では:
ソケットに挿入し、ハウジングの凹溝にレバーの爪を押し込
す。
- コネクタを引き抜く場合、親指でレバー部を押し下げて爪を上昇させ、ワッフルシートを外す。



簡易設定(供給弁 N.C. 仕様の場合)

スイッチ本体に予め設定されている省エネ制御の動作と設定値は以下の通りです。
以下に示す動作にて支障のない場合は、そのままご使用ください。

OUT1 の動作

圧力が設定値(P_1)を超えるとスイッチが ON します。

圧力が設定値(H_1)から応差(H_1)以上下ると、スイッチが OFF します。

工場出荷時は、P_1: -70.0 kPa H_1: 10.0 kPa に設定されています。


OUT2 の動作

吸着指令信号が ON 時に供給弁(OUT2)が開状態となり、真空を発生させ吸着を開始します。
真空度が設定値(P_1)に達すると、供給用バイロット弁を閉状態にします。

その後、真空度が低下する((P_1)から(H_2)下がる)と、再度供給用バイロット弁が開状態となり真空度を保持します。

以降、供給用バイロット弁は開状態、閉状態を繰り返します。

工場出荷時は、H_2: 5.0 kPa に設定されています。






⑥ [F] ボタンを押すと設定が完了します。
出力反転が変更されている場合は、以下が表示され、設定値を変更することができます。
「OUT1 反転出力時」

測定モード → [F] → [H] → [F] → [H] → [F] 完了

機能の設定

■測定モードとは
電源投入後、圧力を検出し表示やスイッチ動作をおこなっている状態を指します。
目的に応じて設定の変更やその他の機能を設定するモードに移行することができる基本モードです。

電源を投入



■ファンクション選択モードとは
測定モードにて [F] ボタンを 2 秒以上押すと [F 0] が表示されます。
この[F 0]を表示し、それぞれの機能の設定を変更するモードを指します。
ファンクション選択モード時に [F] ボタンを 2 秒以上押すと測定モードに戻ります。

供給用バイロット弁 入力禁止範囲の設定	供給用バイロット弁信号 ON 点の入力禁止範囲を設定できます。	1 kPa (H_4)
------------------------	---------------------------------	-------------

●[F 3] から[F 99] の設定項目について

項目	工場出荷時の設定
[F 3] 応答時間の設定	2.5 ms
[F 4] オートリセット機能の設定	手動
[F 6] 表示値微調整の設定	0%
[F 11] 表示分解能の設定	1000 分割
[F 80] 省電力モードの設定	OFF
[F 81] 暗証番号の入力の設定	OFF
[F 90] 全ファンクションの設定	OFF
[F 96] 吸着指令信号の状態確認	OFF
[F 98] 出力確認	通常
[F 99] 出荷状態への復帰	OFF

保守

停電や通電が強制的に遮断された場合の復帰方法

設定に関しては、停電以前の状態に保持されています。
本製品の出力状態は、基本的に停電以前の状態で復帰しますが、ご使用の環境により変化する場合がありますので、ご使用設備全体の安全を確認した後、操作してください。
詳細な管理をしている場合は、ウォーミングアップ(約 10 分)を実施した後、ご使用ください。

トラブルシューティング

■エラー表示機能

異常やエラーが発生したときに、誤りの箇所や種類を表示します。

エラー名称	エラー表示	内容	処置方法
過電流エラー	E-1 E-2	スイッチ出力の負荷電流が 80 mA 以上流れています。	電源を切断して、過電流が発生した出力の要因を取除き再度電源を投入してください。
ゼロクリアエラー	E-3	ゼロクリア操作時、±3.5% F.S. を越えた圧力が加えられています。ただし、1 秒後に自動的に測定モードに復帰します。製品個体差により、±1% F.S. ゼロクリアの範囲が異なります。	加えられている圧力を大気圧状態にしてから再度ゼロクリア操作を行ってください。
加圧エラー	H-H-H	設定圧力範囲の上限を超えた圧力が加えられています。	加えられている圧力を設定圧力範囲内に戻してください。
	L-L-L	設定圧力範囲の下限を超えた圧力が加えられています。	電源を切断し、再度電源を投入してください。復帰しない場合は、当社での調査が必要となります。
システムエラー	E-0 E-4 E-5 E-7 E-8 E-9	内部データエラーの場合、表示されます。	電源を切断し、再度電源を投入してください。復帰しない場合は、当社での調査が必要となります。


仕様

当社ホームページ(URL <http://www.smeworld.com>)より取扱説明書をご確認ください。

SMC株式会社

この内容は予告なしに変更する場合がありますので、あらかじめご了承ください。
© 2022 SMC Corporation All Rights Reserved ZL3-0W00201E

測定モード
↓
[F]ボタン2秒以上押す



■工場出荷時の設定

工場出荷時は次のように設定されています。
設定を変更する場合は、当社ホームページ(URL <http://www.smeworld.com>)より取扱説明書をご確認ください。

●[F 0] 単位切換機能について

単位仕様	工場出荷時の設定
SI 単位固定 単位切替機能付	kPa

●[F 1] OUT1 の設定項目について

項目	説明	工場出荷時の設定
出力反転	スイッチ出力の正反転を、設定することができます。	正転出力
圧力の設定	スイッチ出力の ON 点または OFF 点を設定できます。	-70 kPa (P_1)
応差	応差の設定によりチャタリングを防止することができます。	10 kPa (H_1)

●[F 2] OUT2 の設定項目について

項目	説明	工場出荷時の設定
供給用バイロット弁 信号 ON 点	供給用バイロット弁信号 ON 点を設定できます。	5 kPa (H_2)
供給用バイロット弁 信号 OFF 点	供給用バイロット弁信号 OFF 点を設定できます。	0 kPa (H_3)

■[F 99] 出荷状態への復帰


製品がどのような状態に設定されているか不明になってしまったときに、出荷時の状態へ戻すことができます。

<操作方法>
ファンクション選択モード時に、[F] または [F 0] ボタンを操作し、[F 99] を表示させてください。

[F] ボタンを押します。↓ 出荷状態への復帰に移ります。

出荷状態への復帰

[F] または [F 0] ボタンを押して、



ON

OFF

出荷状態への復帰

設定値

「ON」を表示させ、[F] と [F] ボタンを同時に 5 秒以上押してください。



ON

OFF

中荷能への
休用トライ

休用トライ

出荷状態へ復帰し、
ファンクション選択モード
に戻ります。

[F] (使用しない) 選択時

[F] ボタンを押して設定

ファンクションモードに戻ります。

[F 99] 出荷状態への復帰の設定完了

その他の設定

○ピーク値／ボトルム値表示機能

○ゼロクリア機能

表示値のゼロクリアについて

[F] と [F] ボタンを同時に 1 秒間押すと表示値のゼロ調整を行うことができます。
はじめてご使用になる場合は、圧力が印加されていない状態においてゼロクリアを行ってください。

○キーロック機能

上記設定を行う場合は、当社ホームページ(URL <http://www.smeworld.com>)より取扱説明書をご確認ください。